North America's Leader in Hazardous Material Information Management

1905 Aston Avenue, Carlsbad, CA 92008 Phone (800) 451-8346 Fax (760) 602-8888

# MSDS PRODUCT INFORMATION

Date: 10/07/2005

To: MSDS Requester

From: 3E Company

Subject: The MSDS you have requested

### [ ] MSDS NOT REQUIRED

In response to your request for a Material Safety Data Sheet, according to the OSHA Hazard Communicatin Standard (Right-to-Know), the following item is an article. Articles are defined in 29 CFR 1910.1200(c). Products such as Drugs, cosmetics, food, or alcoholic beverages, wood or wood products, and tobacco or tobacco products, as defined in 29 CFR1910.1200(b)(6), are exempt from the Hazard Communication Standard. Items that are considered articles, as defined in 29 CFR 1910.1200(c), are also exempt from this Standard. Therefore, the manufacturer is not required to provide an MSDS for this product.

#### [X] MSDS DISCONTINUED PRODUCT

In response to your request for a Material Safety Data Sheet, the manufacturer has discontinued the product listed below. The MSDS Attached is the most current version, or an MSDS is no longer available.

### [ ] MSDS BEST COPY AVAILABLE

The MSDS attached is the best copy available from the manufacturer.

### [ ] MANUFACTURER NO LONGER IN BUSINESS

In response to your request for a Material Safety Data Sheet, a current MSDS could not be obtained for this product. It has been determined that the manufacturer listed below is no longer in business. A current address and phone number could not be located.

Manufacturer: Red Devil Incorporated

Product Name: Blacktop & Roof Repair 636 series (DISCONTINED)



# 3E COMPANY North America's Leader in Hazardous Material Information Management

1905 Aston Avenue, Carlsbad, CA 92008

Phone (800) 451-8346 Fax (760) 602-8856

### MSDS DISCONTINUED PRODUCT

Date: 11/08/2001

**To: MSDS Requester** 

From: 3E Company

Subject: The MSDS you have requested

In response to your request for a Material Safety Data Sheet, the manufacturer has discontinued the product listed below. The MSDS attached is the most current version, or an MSDS is no longer available.

Manufacturer: Red Devil Inc.

**ProductName:** Blacktop & Roof Repair 636 series (DISCONTINED)

# Material Safety Data Sheet (MSDS)

Series: #0636, #0637 (All Labels)

NFPA Rating:

1-2-0

HMIS Rating:

1-2-0-B

SECTION I			EMERGENCY TELEPHONE NO			
TRACE NAME (IF NOME, PUT CHEMICAL)	Blacktop & Roof Repair		(918) 825-5744 (24 Hrs.)			
CHEMCAL NAME NIND SYNONYMS						
MANUFACTURER'S MAME AND TELEPHONE NO.	Red Devil, Incorporated	(918) 825-5744				
ACCRESS (Number, Street, City, State, Zip Code)	One Webb Street, Pryor, Okla	homa 74361				

SECTION II - HAZARDOUS INGREDIENTS	%	TLV	PEL	UNITS
PRODUCT CONSISTS OF:				<del>                                     </del>
Calcium carbonate** [1317-65-3] (as nuisance particulate, total)	57.5	10	15	mg/m3
Mineral spirits (petro.dist.) [64742-88-7]	4.2	100	500	ppm
Non-hazardous ingredients*  **Inhalation of particulates unlikely due to product's physical state.	38.3	NE	NE	
*Unlisted ingredients are not considered hazardous under the OSHA Hazard Communication Standard (29 CFR 1910.1200).	i			

SECTION III - PHYSICAL DATA				
SCHLING POINT (*F)	NE	SPECIFIC GRAVITY (H20=1)	1.3-1.5	
VAPOR PRESSURE (MM Mg.)	NE	PERCENT VOLATILÉS' BY VOLUME (%)	< 20	
VAPOR DENSITY (AIR=1)	>1	Н	NA	
SOLUBILITY IN WATER	Insoluble	EVAPORATION RATE	<1.0 (BuAc = 1)	
			<del></del>	

APPEARANCE AND ODOR

Black paste; petroleum distillate odor

SECTION IV - FIRE AND EXPLOSION HAZARD DATA								
FLASH POINT (Method used)	105°F	FLAMMABLE LIMITS	FET	NE	UEL	NE		
EXTINGUISHING MEDIA	Carbon dioxide, dry d	themical, or foam		<del></del>				
SPECIAL FIRE FIGHTING PROCEDURES	Use water spray or fog to cool fire-exposed containers.							
UNUSUAL FIRE AND EXPLOSION HAZARDS	Closed containers ma	y explode when exposed to extreme he	at.			<del> </del>		

# SECTION V - HEALTH HAZARD INFORMATION

### SYMPTOMEFFECTS OR OVEREXPOSURE

Inhalation of dust generated from dried product may cause respiratory irritation. High vapor concentrations may produce headache, dizziness, nausea, and cause eye irritation. Prolonged or repeated skin contact may lead to drying and irritation.

FIRST AID

EYES

Immediately flush eyes with large amounts of water while holding eyelids open. Get medical attention if irritation persists.

SKIN

Wipe material from skin with cloth or paper towel, then wash exposed area with soap and water. Get medical help if irritation persists.

MHALATION

Move victim to fresh air and treat symptomatically.

INGESTION

Contact local poison control center or physician IMMEDIATELY!!

## SECTION VI - REACTIVITY DATA

STABILITY

Normally stable. Avoid heat, open flame.

HICOMPATIBLE MATERIALS

Strong oxidizers

HAZARDOUS DECOMPOSITION PRODUCTS

Carbon monoxide, carbon dioxide

## SECTION VII - SPILL OR LEAK PROCEDURES

PROCEDURES

Depending on extent of spill, wear personal protective equipment (see Sect. VIII) and remove ignition sources. Wipe up with inert absorbent material.

WASTE DISPOSAL METHOD

Waste may be burned in an approved incinerator, or dispose of according to Local, State and Federal regulations.

## SECTION VIII - SPECIAL PROTECTION INFORMATION

RESPIRATORY

Not normally required. If TLV is exceeded, or for symptoms of overexposure, wear a NIOSH-approved respirator for organic vapors.

EYEWEAR

Wear safety glasses.

CLOTHING/GLOVES

Not normally required; in situations of extended skin contact, neoprene or other chemical resistant gloves are recommended.

VENTILATION

Provide adequate general dilution ventilation.

# SECTION IX - SPECIAL PRECAUTIONS

COMBUSTIBLE. Store in a closed container in dry area. This of SARA Title III and 40 CFR 372.65. This product does carcinogenic as listed in the (NTP) Fifth Angual Report of 6

carcinogenic as listed in the {NTP} Fifth Annual Report of

APPROVAL Alem M. Segre

provide one at contin ingredients listed in Section 313

ALAN M. SEGNAS

೯ ಗ್ಯಾಕ್ಷಚಿತ ಗಗ್≎

W/3/4/6

EV DATE

The information contained herein has been developed based upon current available so conclusions of this report obsolete. Therefore, no warranty is extended as to the applications.

y be developed to the transfer of the may ren